ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0432, W0339, W0507, W0446, W0448	NA, I T P L Main Rd, Mani Lyt 5th Crs, Mani Lyt 6th Crs	Ashraya layout cross road
Segment No.	**Total Length (m)**	
11/C-W0432/S093455	133.84	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	61.55	77.535753	13.074217	77.536320	13.074214	Kanaka Road	Ashraya layout
2	72.29	77.535651	13.074893	77.536306	13.074772	Ashraya layout Grave yard	cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads drain and construction of culverts at Ashraya layout cross roads in ward no. 11 Kuvempunagara in Vidyaranyapura sub division	2000000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Concrete road and Solid block drain
Tender	**Work Details**	**Job No. / Work Code**
Tender	Concrete road and Solid block drain	011-17-000025
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/252/2016-17		
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/06/2017	30/06/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Sharath S		0.00
Phone No.	**E-Mail ID**	
9448456136		

Field Inspection Details

Number of Trees

0

Any Other Information

Name

Gugusiddappa c gokule

Date of Inspection

12/07/2017

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0432, W0339, W0507, W0446,

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	12/07/2017	11/08/2017	Approved
SE	K.M. Vasu	12/07/2017	11/08/2017	Verified
EE	H.T. Mohandas	12/07/2017	11/08/2017	Verified
AEE	Shivakumar m goudar	12/07/2017	11/08/2017	Verified
AE	Gurusiddappa C Gokhale	12/07/2017	11/08/2017	Mobile verification done
AE	Gurusiddappa C Gokhale	12/07/2017	11/08/2017	Forwarded



Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0432, W0339, W0507, W0446,